




A Halloween horror story at Excelsior Motors

A customer brings in his 72 SM for a windshield after a minor mishap in the storage garage. The car is a California car with good paint showing little to no rust. The windshield comes off with little drama except that the wrong adhesive was used which made cleaning the channels take a bit more time. The A pillars channels look pretty good with a bit of surface rust. The roof channel looks pretty good. The horror comes along the bottom edge of the windshield. A previous fix was amateurish at best, a dishonest cover up at worst. Rust holes at the base of the windshield were filled with epoxy and strips of sheet metal glued over the larger holes. The result was bigger and deeper rust holes that grew with the cover-up job. See below if you dare.



The Repair

Below is the repair section that will be welded in after the rusty section is removed. The A pillar and roof sections will not be used in the repair. More pictures will be posted as the job progresses.



Replacement piece cut and ready to be welded in.



Welding in the repair panel



Ready to install the windshield



The finished product, ready to install wipers!

